

ATTACHMENT 3 – PHOTOGRAPHS

In addition to the plants pictured below, also observed in the PEM area were *Pontederia cordata* (pickerelweed), *Mentha spp.* (mint), *Iris*, and *Typha spp.* (cattail). Vegetation in the PFO areas included *Acer negundo* (box elder), *Fraxinus pennsylvanica* (green ash), *Toxicodendron radicans* (poison ivy), *Plantanus occidentalis* (American sycamore), and *Acer saccharinum* (silver maple).



Picture 4645 – Wetlands Wildlife: turtle possibly laying eggs on western side of Wetland 13



Picture 4646 – Looking West at Tidal Wetland along western end of Wetland 13. Emergent plants are believed to be *Polygonum pennsylvanicum* L. (Lady’s thumb smartweed).



Picture 4647 – Up on bank from Tidal Wetland looking west at Wetland 13



Picture 4648 – Part of wet 13 – westernmost finger looking south



Picture 4649 – Wetland 13a, looking east at PEM wetland bordered by PFO wetland 13 on south



Picture 4650 – PEM Wetland 13a, looking east



Picture 4651 –Close up of *Nuphar advena* (Spatterdock) in flower. To immediate left are two *Impatiens capensis* (jewelweed).



Picture 4652 – *Nuphar advena* (Spatterdock)



Picture 4653 – Looking west up Cameron Run at PEM wetland 13a




Picture 4654 – *Peltandra virginica* (Arrow arum) in flower.



Picture 4655 – Group of plants on right side, believed to be *Polygonum pennsylvanicum* L. (Lady's thumb smartweed) next to *Peltandra virginica* (Arrow arum).



Picture 4656 – PEM Wetland 13b, looking east. Dominant plant is Nuphar advena (spatterdock).



4657 – Wetland 13a looking west



Picture 4658 – Linear wetland feature coming south from wetland 13, PFO



Picture 4659 – Culvert, connected to wetland 13 by linear wetland feature shown in picture 4658



Picture 4660 – Sewer Manhole Cover



Picture 4661 – Abandoned building inside fence