

Fairfax County 2016 MS4 Program Plan and Annual
Report

Appendix R12

List of Locations Upon Which Dry Weather Screening was
Conducted

VSMP Permit Number VA0088587
9-30-2016

Fairfax County 2016 MS4 Program Plan and Annual Report
Appendix R12
Page 1 of 3

Stormnet ID	Results of Inspection	Follow-up Actions
STMN0174007118	No Exceedances	
STMN0174007371	No Exceedances	
STMN0181006289	No Exceedances	
STMN0181006504	No Exceedances	
STMN0253413937	Copper Exceedance	Retest on 10/20/15 by CG and DW resulted in Copper of 0.0 mg/l. Trackdown not necessary.
STMN0262013002	No Exceedances	
STMN0262014322	No Exceedances	
STMN0271011330	No Exceedances	
STMN0271011409	Copper and Specific Conductance Exceedance	Retest on 10/20/15 by CG and DW resulted in Copper below levels but SpCond still above exceedance. Trackdown was unable to locate source. Could not track flow, possible groundwater input. Good candidate to be reinspected in 2016.
STMN0284015328	Fluoride and Detergents Exceedance	Retest on 10/27/15 by CG and JS resulted in continued exceedences of Fluoride. Trackdown resulted in possible cooling tower discharge. Site was turned over to IHRR via email on 10/30/15.
STMN0292013522	No Exceedances	
STMN0292013841	Copper and Fluoride Exceedance	Retest on 10/26/15 by CG and EA resulted in continued exceedences at east inlet and none in west inlet. Trackdown resulted in possible cooling tower. Site turned over to IHRR via email on 10/30/15.
STMN0293017344	No Exceedances	
STMN0293017455	No Exceedances	
STMN0294019414	No Exceedances	
STMN0303413246	No Exceedances	
STMN0303413551	No Exceedances	
STMN0303507866	No Exceedances	
STMN0353028854	No Exceedances	
STMN0354027678	No Exceedances	
STMN0383025912	No Exceedances	
STMN0383026327	No Exceedances	
STMN0442032599	No Exceedances	
STMN0442032617	No Exceedances	
STMN0442032770	No Exceedances	
STMN0442032789	No Exceedances	
STMN0442033087	No Exceedances	
STMN0442033318	No Exceedances	
STMN0442033423	No Exceedances	
STMN0442033735	No Exceedances	
STMN0443038891	Copper, Phenol and Specific Conductance Exceedance	Retest on 10/22/15 by CG and JS led to no exceedances. Took samples from upstream manholes. Smell of dead animal coming from manhole. Slightly turbid water could have resulted in original exceedances.
STMN0453040272	No Exceedances	
STMN0454058748	No Exceedances	
STMN0474036651	No Exceedances	
STMN0474036969	Copper and Fluoride Exceedance	Retest visit on 10/27/15 by CG and JS yielded no flow in the manhole.
STMN0474037687	No Exceedances	
STMN0474037745	No Exceedances	
STMN0474039318	No Exceedances	
STMN0482420141	No Exceedances	
STMN0483425638	No Exceedances	
STMN0483425879	No Exceedances	
STMN0484082544	No Exceedances	
STMN0484512314	No Exceedances	
STMN0494423244	No Exceedances	
STMN0543048132	No Exceedances	
STMN0543048357	No Exceedances	
STMN0543048461	No Exceedances	

Stormnet ID	Results of Inspection	Follow-up Actions
STMN0544047677	Fluoride and Detergents Exceedance	Retest on 10/23/15 by CG and JB resulted in FI exceedance. Followed flow to water line leak next to apartment building. Contacted management of Bent Tree Apartments and informed of leak. Leak was fixed and retest 11/23/15 yielded no exceedances.
STMN0553436774	No Exceedances	
STMN0562053117	No Exceedances	
STMN0562055203	No Exceedances	
STMN0573435701	No Exceedances	
STMN0582430267	No Exceedances	
STMN0584434437	No Exceedances	
STMN0651048577	No Exceedances	
STMN0651048611	No Exceedances	
STMN0651048948	No Exceedances	
STMN0651049383	No Exceedances	
STMN0661444482	No Exceedances	
STMN0693448571	No Exceedances	
STMN0693448573	No Exceedances	
STMN0712436948	No Exceedances	
STMN0714445172	No Exceedances	
STMN0723445025	Copper and Specific Conductance Exceedance	Retest on 11/16/15 by CG and JS resulted in no exceedances,
STMN0771459307	No Exceedances	
STMN0801455141	No Exceedances	
STMN0801455199	No Exceedances	
STMN0802454794	No Exceedances	
STMN0811512567	No Exceedances	
STMN0902474253	Fluoride Exceedance	Broken water main repaired. Retest on 11/4/15 by DW and JB resulted in dry outfall.
STMN0903482034	No Exceedances	
STMN0923479988	No Exceedances	
STMN0924479464	No Exceedances	
STMN0924479470	No Exceedances	
STMN0924479620	No Exceedances	
STMN0991488348	No Exceedances	
STMN0991489059	No Exceedances	
STMN0991505083	No Exceedances but suspected upstream car washing	Sent to IHRR on 11/3/15 for possible car washing at collision center. Berm was built to contain washwater inside facility.
STMN0992487673	No Exceedances	
STMN0992487769	No Exceedances	
STMN0992487937	Copper, Phenol and Detergents Exceedance	Retest on 11/16/15 by CG and JS resulted in tests below exceedance levels.
STMN0992488056	No Exceedances	
STMN0992488339	No Exceedances	
STMN0992515938	No Exceedances	
STMN0993516398	Copper Exceedance	Site was turned over to IHRR via email on 11/5/15 for possible cooling tower discharge.
STMN1011486767	No Exceedances	
STMN1011486796	No Exceedances	
STMN1011486824	No Exceedances	
STMN1011486878	No Exceedances	
STMN1011486882	No Exceedances	
STMN1011486934	No Exceedances	
STMN1013494095	pH Exceedance	Retest on 12/8/15 by CG and JW resulted in test below exceedance level.
STMN1013494214	No Exceedances	
STMN1013494505	No Exceedances	
STMN1013494544	No Exceedances	
STMN1013494557	No Exceedances	
STMN1074058314	No Exceedances	
STMN1074501699	No Exceedances	

Stormnet ID	Results of Inspection	Follow-up Actions
STMN1133058249	No Exceedances	
STMN1133081801	No Exceedances	
STMN1134502798	No Exceedances	