

COMMONWEALTH of VIRGINIA

DEPARTMENT OF ENVIRONMENTAL QUALITY

Molly Joseph Ward Secretary of Natural Resources NORTHERN REGIONAL OFFICE 13901 Crown Court, Woodbridge, Virginia 22193 (703) 583-3800 www.deq.virginia.gov

David K. Paylor Director

Thomas A. Faha Regional Director

May 5, 2016

VIA EMAIL: https://www.ubayee.com

Larry Bayne Lorton Construction Landfill 10001 Furnace Road Lorton, Virginia 22079

INSPECTION REPORT - NO DEFICIENCY

Re: Lorton CDD Landfill – 10001 Furnace Road, Lorton Solid Waste Permit (SWP) 331

Dear Mr. Bayne:

On April 25, 2016, the Virginia Department of Environmental Quality Northern Regional Office conducted an inspection of the Lorton CDD Landfill operating under SWP 331. During this inspection, the facility was evaluated for compliance with the Virginia Waste Management Law and Regulations (9 VAC 20-81-10 *et seq.*) and SWP 331.

During the inspection no apparent violations of SWP 331 or the Virginia Waste Management Law and Regulations (9 VAC 20-81-10 *et seq.*) were observed. A copy of the inspection checklist is enclosed.

If you have any questions, please contact me at (703) 583-3832.

Sincerely,

Jeffrey Modliszewski Solid Waste Inspector

cc: CASE FILE Crystal Hambrick, Fairfax County

Commonwealth of Virginia Department of Environmental Quality

Permit No.: SWP331 Insp. Date: 25-APR-16

CDD Landfill [SW] Inspection Report				
acility Name: Lorton Construction	on Landfill Permit No.	: SWP331		
egion: Northern Regiona	I Office Inspection E	Inspection Date: 25-APR-16		
spected By: Modliszewski, Jef				
Reference	Description	SIA	v c	
10.1-1408.1	Disclosure Statement	IX	0	
10.1-1408.2	Operator Certification	II X	(
20-70-10 et seq.	Financial Assurance		(
20-90-10 et seq.	Permit Action Fees		(
20-81-80	Waste Assessment Program	IX	(
20-81-100.B	Compliance with the facility's permit	II	(
20-81-100.E	Unauthorized waste program and inspection	IIX	(
20-81-110.B	Prohibited waste		(
20-81-130	Facility design / construction			
20-81-140.A.1,4	Safety and fire control	IIX	(
20-81-140.A.6	Pollutant discharge			
20-81-140.A.7	Stormwater control system maintenance			
20-81-140.A.8,14-15	Facility operation, maintenance, and training			
20-81-140.A.9-13	Hazard and nuisance control	IX		
20-81-140.A.16	Facility self inspections	IX		
20-81-140.A.17	Record maintained of waste received and processed			
20-81-140.C	Compaction and cover	IX		
20-81-160	Closure requirements			
20-81-170	Post-closure care requirements	11		
20-81-200	Decomposition gas control	II X		
20-81-210	Leachate control	11		
20-81-250	Groundwater monitoring program I		(
20-81-260	Corrective action program	11	(
20-81-485	Operations Manual			
20-81-530	Permittee recordkeeping and reporting	II		
20-81-610-660	Special Waste II		(

20-81-485

CDD Landfill [SW] General Comments			
10.1-1408.1	The August 20, 2015 Disclosure Statement identifies the following as Key Personnel: Dean Kattler, Jim Alderson, Gary Hewes, James Stenborg, and Larry Bayne.		
10.1-1408.2	The facility has one licensed facility operators listed as a Key Personnel: Larry Bayne (License Number 4605002098 which expires on December 31, 2016).		
20-81-80	The 2015 SWIA for was accepted by the DEQ on April 8, 2016.		
20-81-100.E	The facility documented that it was inspecting 10% of the incoming loads of waste generated outside of Virginia. The facility reviewed a portion of the unauthorized waste program during the weekly safety training.		
20-81-140.A.1,4	The facility conducted weekly safety training. The safety training log was reviewed; it contains documentation of safety topics.		
20-81-140.A.9-13	Litter was being picked up during the inspection. The facility documented when additional personnel were used to pick up litter.		
20-81-140.A.16	The facility conducted self inspections in February and March 2016. The landfill gas remediation system is not included on the site inspection checklist, it is inspected separately.		
20-81-140.C	The facility was operating two working faces during the inspection; the facility had an adequate amount of equipment to handle the incoming waste. The landfill's progressive cover was inspected; partially exposed waste was observed on the Northwestern and Eastern slopes. The facility was addressing the exposed waste during the inspection.		
20-81-200	Methane concentrations were not detected above the reportable limit during the March 7, 2016		

Overall Inspection Comments

monitoring event.

On April 25, 2016, at approximately 9:00 a.m. Jeffrey Modliszewski a representative from the Virginia Department of Environmental Quality (DEQ) arrived at the Lorton Construction Landfill, SWP 331. The DEQ representative was greeted by Larry Bayne. Mr. Bayne escorted the DEQ representative throughout the compliance inspection. The DEQ staff conducted an exit interview with Mr. Bayne to discuss the findings of the inspection.

Larry Bayne recertified the operations manual on June 7, 2015.

PLEASE advise the Regional Office within 10 calendar days if any information noted in this report is incorrect, if you have taken appropriate action to meet compliance, or if there is other information that the department should consider regarding these alleged violations.

PLEASE be advised that this report is not an agency proceeding or determination which may be considered a case decision under the Administrative Process Act (Va.Code 2.2-4000 et seq). If informal discussions do not lead to a satisfactory conclusion on the contents of this report, you may request in writing that DEQ take all necessary steps to issue a final decision or fact finding under the APA on whether or not a violation has occurred.

Modliszewski, Jeffrey (DEQ)

From:	Modliszewski, Jeffrey (DEQ)
Sent:	Thursday, May 05, 2016 9:30 AM
То:	Larry Bayne (lbayne@esiwaste.com)
Cc:	Crystal.Hamrick@fairfaxcounty.gov
Subject:	SWP331 Inspection
Attachments:	SWP331 CIR ND 20160505.pdf

Larry

I have attached the inspection report from last week's inspection. Thanks jrm

Jeffrey Modliszewski Environmental Specialist II Phone: 703-583 3832 Email: Jeffrey.modliszewski@deq.virginia.gov