


Additional Impervious Area in Seaward 50 feet



The increase in impervious in the seaward 50 feet is approximately 30 sq. ft.