LEGEND

- st — storm sewer
- ? — suspected utility
- #? — suspected utility, amount # stacked vertically
- chain-link fence
- 001S — 001E — GPR profile start (S) and stop (E)
- metal-detector anomaly
- tunnel sections found with GPR
- bricked tunnel section
- tunnel section, with VT-150 parallel crawler
- collapsed tunnel
- exploratory drilling hole
- catch basin
- parking lot lamp
- manhole cover
- utility pole
- aboveground storage tank
- sunken soil depression
- current building
- electrical conduit bank

N

approximately

30 15 0 15 30 ft

Scale: One inch equals approximately thirty feet

NACVA GEOPHYSICS, INC.
Subsurface Geophysical Surveys
225 N. Route 303, Suite 102
Congers, NY 10920
(845)268-1800
(845)268-1802 FAX

Prepared for:

APEX

8854 Rixlew Lane
Manassas, Virginia

Plate 1: Tunnel System of Workhouse Arts Center
9601 Ox Road, Lorton, VA

Client	Apex Companies, LLC	Date of Work	March 16 - 27, 2015
Project No.	C15031611	Map By	Daniel Latini

ALL UNDERGROUND FACILITIES MAY NOT BE DEPICTED ON THIS MAP