



Vendor Access to PLUS

Test Report Look up by Project Name,

Step 1. Open Cross Connection Web Page and go to link in Download test report box.



Step 2. Click on the building tab and scroll down to the General search



Step 3. Enter the Project Name and Click Search.

General Search General Search

Search All Records

Record Number Record Type

Project Name
Coppermine Crossing

Start Date End Date

License Type State License Number County License #

First Last Name of Business

Street Number Street Prefix Street Name Street Type

Unit Type Unit #

City State Zip Code

Country/Region

Parcel ID Number

▶ Search Additional Criteria

Search **Clear**

Step 4. Click on the Reports Link in the upper right corner and click Backflow Assembly Test Report

FAIRFAX COUNTY
VIRGINIA

Register for an Account **Reports (1)** Help Login

PLUS TEST ENVIRONMENT to access

Reports (1):
Backflow Assembly Test Report

Home **Building** Enforcement Environmental Health Fire Planning Site Zoning

Search Applications Schedule an Inspection


Record XC-93198227: COPPERMINE CROSSING

Cross Connection


Record Status: Active

Record Info Payments Parcel Information


Step 5. For Related Record's Test Reports click on Record Info Tab and Click Related Records.



Step 6. Each Test Report will need to be downloaded individually by clicking view next to the Record and repeat Step 4.



Test Reports can also be retrieved by Clicking **Record info, Attachment's, first attachment and then open File** where it can be printed or saved.



Home **Building** Enforcement Environmental Health Fire Planning Site Zoning

Search Applications Schedule an Inspection

Record XC-93198227: COPPERMINE CROSSING

Cross Connection

Record Status: Active

Record Info Payments Parcel Information

Attachments

The maximum file size allowed is **1000 MB**.

Name	Share Link	Type	Size	Latest Update	Action
BA_Test_Report_20220920_093411.pdf	Copy Link	Test Report Due	353.08 KB	09/20/2022	Actions
BA_Test_Report_20220920_110926.pdf	Copy Link	Test Report Due	353.08 KB	09/20/2022	Actions

Home **Building** Enforcement Environmental Health Fire Planning Site

Zoning

Search Applications Schedule an Inspection

Record XC-93198227: COPPERMINE CROSSING

Cross Connection

Record Status: Active

Record Info Payments Parcel Information

Attachments

The maximum file size allowed is **1000 MB**.

BA_Test_Report_20220920_093411.pdf

Downloads

- BA_Test_Report_20220920_093411.pdf
Open file
- BA_Test_Report_20220920_110926.pdf
Removed
- BA_Test_Report_20220920_093411.pdf
Removed
- BA_Test_Report_20220920_113626 (1).pdf
Removed
- BA_Test_Report_20220920_113626.pdf
Removed
- inspectionlist20220922.csv
Removed
- RecordSummary_20220920_144742.pdf
Removed
- IMG_1314.JPG
Removed
- inspectionlist20220921 (1).csv
Removed