
LAUREL HILL HOUSE


Historic Structure Report and Treatment Options





A. Site Plan







- 6. early 20th century
- 7. early 20th century
- 8. early 20th century
- 9. early 20th century, before 1920
- 10. early- to mid-20th century, c. 1937

Note: Addition #9 refers to the second floor shed dormers (not shown on this drawing)


First Floor Proposed Building Sequence Plan Additions numbered as noted in text above. (H-1)










C. Existing Conditions/Historic Analysis Floor Plans continued




C. Existing Conditions/Historic Analysis Floor Plans continued









C. Existing Conditions/Historic Analysis Floor Plans *continued*








C. Existing Conditions/Historic Analysis Floor Plans continuedC.



























Option 1: Restoration of the original 18th Century house with new contemporary compatible addition.




RESTORED BTH CENTURY HOUSE PROPOSED ADDITION



V. DRAWINGS

Option 1: Restoration of the original 18th Century house with new contemporary compatible addition.




Option 2: Rehabilitation of house in its current configuration.





Option 2: Rehabilitation of house in its current configuration.

NOTE: STABILIZE FOUNDATION AND MAKE IMPROVEMENTS AS NEEDED FOR SAFETY AND SECURITY. ADD INTERPRETIVE SIGNAGE WITH HISTORICAL INFORMATION ABOUT THE BUILDING.



V. DRAWINGS

Option 3: Selective demolition to foundation. Preserve foundations and interpretive treatment plan.